## Message

From: Lobik Stephen [slobik@facil.umass.edu]

Sent: 10/19/2010 1:23:24 PM
To: rjarosz@ingledc.com

CC: Pocsik Mark [mpocsik@facil.umass.edu]; Hanchett, James (DPH) [James.Hanchett@state.ma.us]

Roger,

How are you doing on the items below.

- 1. Steel on back side of door into 224B
- 2. Strike installed in jamb. We need this ASAP or else the alarm will go off because the door cannot be secured.
- 3. Deadbolt in door between 224A and 224.

Thanks,

Stephen

Stephen Lobik

Capital Project Manager

Facilities & Campus Planning Division

University of Massachusetts

(T) 413-545-6516



(F) 413-545-3684

slobik@facil.umass.edu